

Certificate of Test

Client: DuraPlas, Inc.
16400 Midway Road
Addison, TX 75001

Date: 6 November 2020

SES Document No.: 1754744-TS-CT-01 (Rev 0)

Project Manager: Jason Bryan, PE

Client Contact: Andrew Dulac

Date of Testing: 30 October 2020

Project/Test Description: 24" TuffStand – Compression load test to breakage
Test Conditions: Flat surface, longitudinal dunnage, or transverse dunnage


Test Sample Identification: DuraPlas, Inc. 24" TuffStand
Quantity: 10 samples
Material: Torzen T3000HSL Injection Molding Resin

Test Equipment: Load Cell, 100 kip [S/N: 3080] Computerized Data Acquisition System
SES Vertical Load Frame, 750-kip Configuration String Potentiometers

Procedure: A compressive load was applied to the pipe support sample through a client-provided 24" half-pipe fixture with the samples on a flat surface, with longitudinal dunnage, or with transverse dunnage until failure. All tested was performed at an ambient temperature between 60 °F – 70 °F.

Results: Flat Surface, Seven Samples – Peak Load: 77,040 lbf (Average) / 1,290 lbf (Std. Dev)
Longitudinal Dunnage, Two Samples – Peak Load: 46,877 lbf and 44,865 lbf
Transverse Dunnage, One Sample – Peak Load: 72,721 lbf

Prepared by: _____
Jason Bryan, PE
Associate II

Reviewed by:  _____
George Ross, PhD, PE
Principal



4. Results

4.1 Summary

Table 1: Summary of test results.

Sample ID#	Dunnage	Avg. Disp. Rate (mils/min)	Disp. to Peak Load (mils)	Peak Applied Load (lbf)	Breakage Description
1	-	-1,653	1,273	-76,449	Crumpling of top of side walls/corners at pipe saddle valley.
2	-	-1,012	1,469	-76,110	Crumpling of top of side walls/corners at pipe saddle valley.
3	-	-1,501	1,054	-74,656	Crumpling of top of side walls/corners at pipe saddle valley.
4	-	-1,949	1,112	-78,386	Crumpling of top of side walls/corners at pipe saddle valley.
5	-	-1,777	1,204	-77,290	Crumpling of side walls/top corners. Continued loading beyond peak caused additional crumpling.
6	-	-1,608	1,166	-77,862	Crumpling of side walls/top corners. Continued loading beyond peak caused additional crumpling.
7	Longitudinal	-2,103	1,446	-46,877	Crumpling of middle of side walls, crack on base flange at/near interface with dunnage corner.
8	Longitudinal	-2,328	1,167	-44,865	Crack on base flange at/near interface with dunnage corner.
9	Transverse	-1,641	1,425	-72,721	Catastrophic crack through base flange and up the side wall initiating at/near interface with dunnage corner.
10	-	-1,670	1,027	-78,524	Crumpling of top of side walls/corners at pipe saddle valley.

Note: 1 in = 1,000 mils